

Kątowniki nierównoramienne

| wymiary mm | waga kg/m | gatunek i stan utwardzenia |
|---------------|-----------|----------------------------|
| | | 6082 T6 |
| 15 x 10 x 2 | 0,12 | ● |
| 20 x 10 x 2 | 0,15 | ● |
| 20 x 15 x 2 | 0,18 | ● |
| | | |
| 18 x 18 x 2 | 0,18 | ● |
| 20 x 15 x 3 | 0,26 | ● |
| 25 x 10 x 2 | 0,18 | ● |
| 25 x 15 x 2 | 0,21 | ● |
| | | |
| 25 x 15 x 2,5 | 0,26 | ● |
| 25 x 15 x 3 | 0,31 | ● |
| 25 x 20 x 2 | 0,23 | ● |
| 25 x 20 x 3 | 0,35 | ● |
| 30 x 10 x 2 | 0,21 | ● |
| 30 x 15 x 2 | 0,23 | ● |
| 30 x 15 x 3 | 0,34 | ● |
| 30 x 20 x 2 | 0,26 | ● |
| 30 x 20 x 2,5 | 0,33 | ● |
| 30 x 20 x 3 | 0,38 | ● |
| 30 x 20 x 4 | 0,50 | ● |
| 30 x 25 x 2 | 0,29 | ● |
| 30 x 25 x 3 | 0,43 | ● |
| 35 x 20 x 2 | 0,29 | ● |

| | | | |
|---------------|------|---|---|
| 35 x 20 x 3 | 0,42 | ● | - |
| 35 x 25 x 3 | 0,46 | ● | - |
| 40 x 10 x 20 | 0,26 | ● | - |
| 40 x 15 x 2 | 0,29 | ● | - |
| 40 x 20 x 2 | 0,31 | ● | - |
| 40 x 20 x 2,5 | 0,40 | ● | - |
| 40 x 20 x 3 | 0,46 | ● | - |

| | | | |
|-------------|------|---|---|
| 40 x 20 x 4 | 0,61 | ● | - |
| 40 x 25 x 2 | 0,34 | ● | - |
| 40 x 25 x 3 | 0,50 | ● | - |
| 40 x 25 x 4 | 0,66 | ● | ■ |
| 40 x 30 x 2 | 0,37 | ● | - |
| 40 x 30 x 3 | 0,54 | ● | - |
| 40 x 30 x 4 | 0,71 | ● | - |
| 45 x 10 x 2 | 0,29 | ● | - |
| 45 x 20 x 2 | 0,35 | ● | - |
| 45 x 30 x 3 | 0,58 | ● | - |
| 50 x 15 x 2 | 0,34 | ● | - |
| 50 x 15 x 3 | 0,51 | ● | - |
| 50 x 20 x 2 | 0,37 | ● | - |

| | | |
|---------------|------|---|
| 50 x 20 x 2,5 | 0,46 | - |
| 50 x 20 x 3 | 0,54 | - |
| 50 x 25 x 2 | 0,39 | - |
| 50 x 25 x 2,5 | 0,50 | - |
| 50 x 25 x 3 | 0,58 | - |
| 50 x 25 x 4 | 0,77 | - |
| 50 x 30 x 2 | 0,42 | - |
| 50 x 30 x 3 | 0,62 | - |
| 50 x 30 x 4 | 0,82 | - |
| 50 x 30 x 5 | 1,01 | - |
| 50 x 40 x 2 | 0,48 | - |
| 50 x 40 x 3 | 0,71 | - |
| 50 x 40 x 4 | 0,93 | - |
| 50 x 40 x 5 | 1,17 | - |
| 60 x 15 x 2 | 0,39 | - |
| 60 x 20 x 2 | 0,42 | - |
| 60 x 20 x 2,5 | 0,53 | - |
| 60 x 20 x 3 | 0,62 | - |
| 60 x 25 x 2,5 | 0,57 | - |
| 60 x 25 x 3 | 0,66 | - |

| | | |
|---------------|------|---|
| 60 x 30 x 2 | | - |
| | 0,48 | ● |
| 60 x 30 x 3 | | - |
| | 0,71 | ● |
| 60 x 30 x 4 | | - |
| | 0,93 | ● |
| 60 x 30 x 5 | | - |
| | 1,15 | ● |
| 60 x 40 x 2 | | - |
| | 0,53 | ● |
| 60 x 40 x 3 | | - |
| | 0,79 | ● |
| 60 x 40 x 4 | | - |
| | 1,04 | ● |
| 60 x 40 x 5 | | - |
| | 1,28 | ● |
| 60 x 40 x 6 | | - |
| | 1,52 | ● |
| 70 x 15 x 2 | | - |
| | 0,45 | ● |
| 70 x 20 x 2 | | - |
| | 0,48 | ● |
| 70 x 25 x 2,5 | | - |
| | 0,62 | ● |
| 70 x 30 x 2 | | - |
| | 0,54 | ● |
| 70 x 30 x 3 | | - |
| | 0,80 | ● |
| 75 x 50 x 5 | | - |
| | 1,62 | ● |
| 80 x 15 x 2 | | - |
| | 0,50 | ● |
| 80 x 20 x 2 | | - |
| | 0,53 | ● |
| 80 x 25 x 2 | | - |
| | 0,57 | ● |
| 80 x 25 x 2,5 | | - |
| | 0,69 | ● |

| | | |
|---------------|------|---|
| 80 x 30 x 3 | 0,87 | - |
| 80 x 40 x 2 | 0,64 | - |
| 80 x 40 x 3 | 0,95 | - |
| 80 x 40 x 4 | 1,25 | - |
| 80 x 40 x 6 | 1,85 | - |
| 80 x 50 x 2 | 0,69 | - |
| 80 x 50 x 6 | 2,05 | - |
| 80 x 60 x 4 | 1,50 | - |
| 80 x 80 x 8 | 3,28 | - |
| 100 x 20 x 2 | 0,64 | - |
| 100 x 30 x 3 | 1,03 | - |
| 100 x 40 x 4 | 1,47 | - |
| 100 x 50 x 3 | 1,19 | - |
| 100 x 50 x 4 | 1,61 | - |
| 100 x 50 x 5 | 1,96 | - |
| 100 x 50 x 6 | 2,34 | - |
| 100 x 50 x 8 | 3,12 | - |
| 100 x 50 x 10 | 3,78 | - |
| 100 x 60 x 6 | 3,20 | - |
| 120 x 20 x 2 | 0,76 | - |

| | | |
|----------------|------|--|
| 120 x 40 x 4 | 1,69 | |
| 120 x 50 x 3 | 1,36 | |
| 120 x 60 x 6 | 2,82 | |
| 120 x 60 x 8 | 3,78 | |
| 120 x 80 x 10 | 5,13 | |
| 130 x 30 x 3 | 1,30 | |
| 140 x 50 x 3 | 1,53 | |
| 150 x 50 x 4 | 2,12 | |
| 150 x 75 x 8 | 4,77 | |
| 150 x 75 x 10 | 5,91 | |
| 150 x 100 x 5 | 3,37 | |
| 150 x 100 x 10 | 6,60 | |
| 160 x 50 x 3 | 1,68 | |
| 180 x 150 x 6 | 5,35 | |
| 200 x 100 x 10 | 7,83 | |

PN-EN 573-3 Skład chemiczny
 PN-EN 755-1 Warunki techniczne kontroli i dostawy
 PN-EN 755-2 Własności mechaniczne
 PN-EN 755-9 Tolerancje wymiaru i kształtów

 - ze składu
 - na zamówienie